


Accessories

E18401

Sensor Testpak

TestPak E18401 may no longer be available from IFM. This was replaced by E18430, however, this TestPak has proven to be unreliable to reprogram the IFM flow switch. The recommendation would be to replace the flow switch rather than reprogram the existing switch until a new TestPak can be developed by IFM Electronic.



Design	for 2-wire, 3-wire and 4-wire sensors with remote teach
Supply	6 x Alkaline AA
Output voltage [V]	24 DC $\pm 5\%$
Output current [mA]	100
Ambient temperature [°C]	-20...40
Weight [kg]	0.256