



GRBA0PDKF0L8C0305K0CFLNPG30  
 1882656.001  
 K220188265601001

3/1/2024

Factory Wiring  
 Field Wiring

Terminal Block  
 Connection  
 No Connection

Warning: Disconnect and Lockout Power before servicing. Any Replacement wire must be copper with a temp. rating of 105 deg. C. Refer to the installation instructions for piping, venting and start-up procedures.

Caution - Never jumper or disconnect any factory wiring. Consult the manufacturer before making any modifications.

Note: Optional Relays K1 and K2 are plug-in type, and can be mounted on the Main Connection Board in the Electrical Cabinet.